

1

Sent to Chief Surveyors 19-5-17

Received from Chief Surveyors

VESSEL'S NAME Sheliss Mundetta Report H-20 No. 1165-**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey 1st Eng -

When due

* 100 A-1 (Steel)

2 Dks (Steel)

Cell DB 302' 1051E. F.P.T. 152E. A.P.T. 317E

FK. Two DK bulkheads in forward & after holds disposed with
4 BH to upper deck 2 BH to 2nd Dk only

Cen. A + CP P 27' B 104' F 22'

M

It is suggested that two side stringers
are fitted in way of web frames in ESB space as
shown on plan by 7/6/17. The stringers should
state of this ship. & also that the depth of
amidships is 17 feet.

M

S/O 2/6/17



© 2021

Lloyd's Register
Foundation

009067-009073-0095