

10m, 11.20.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

Steel S.S. "WRAY CASTLE".

Rpt.

Fal.

No. 6025.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

ture of Survey

Before this case receives consideration the Surveyors should be requested to state whether the particulars given in the report regarding the frame spacing ^m peaks, width and thickness of upper deck ~~the~~ stringer plate, size of propeller post & riveting in butts of outside plating, are correct.

They should also state the number and particulars of side stringers, size of upper deck stringer angle, if 2 web frames are fitted forward as per plans, whether the butts of upper deck stringer plate are quadruple riveted for half length in wells, particulars of steam and hand steering gear, the length of erections. length and capacities of double bottom and peak tanks, and the other particulars required on page four of the report.

They should also endeavour to ascertain the type of stockless anchors, and where the anchors and chain cables were tested.

The report should be returned to the Surveyors for corrections as necessary.

Dr. 24.6.21.

in book 2/1/21



2021

24. 6. 21.

Lloyd's Register Foundation

009067-009073-0344

Material and thickness