

Received from Chief Ship Surveyor

14 SEP 1959

SHIP'S NAME "RESTAURADOR"

REPORT B.As.

No. 30691

GB

Outstanding Conditions of Class: SUBJECT to shell plating (holed)  
(s.s.a) in 1st below sheerstrake being specially examined and  
dealt with as necessary next drydocking.

S.R.L. Appendix. ~~(As before or None)~~

Nature of Present Survey: (Afloat and in dry dock)

Docking: Examination and repairs on account of grounding damage.


Recommendation:

SUBMITTED record of 'DS 6,59' be assigned  
as recommended, subject as above, and to rudder  
stock (twisted 7°) being specially examined and dealt  
with as found necessary by the next drydocking.

DS 6,59 Subject


INSERT IN S.R.L. APPENDIX.  
(Rudder stock twisted 7° (2,59)).

ENGRS. SURVEYORS TO NOTE



© 2020

C.S.S. Register Dept.  
to note.



Register  
Foundation

*James*  
11/9/59.