



Repairs, Etc., of Engines and Boilers

Now done:

Back ends of furnaces cleaned.

Furnaces and smoke tubes scaled.

Water tubes turbed.

Boilers tested hydraulically to 300 lbs. found tight.

Two (2) plugged water tubes in outboard furnace of Starboard Boiler were not replaced at this time as new tubes were not available.

W. B. Cowen  
Surveyor.

Boiler  
Subject recommended and  
checked by Starboard  
gauge connection as the next  
For inspection & Classification  
Survey to be done on 7-7-68

W. B.  
3/8/68

