



The steam machinery removed & steel spines  
 & 2 water tube donkey boilers built N.Y. - If this report is copied by copying Press, especial care must be taken that the copying paper is not so much damp as to spread the ink, or to cause it to show through to the other side,  
 under special tray, fitted.

to MC 12-26.  
 + NE 12-26.  
 2 WTD 26. 2500

OIL ENGINES  
 80y 250 SA  
 30"-42"

NHP 1262

BUICK-SWITZER REVER  
 ENGINE Co.  
 ST. LOUIS, Mo.

BRKSTN 12-26

Report  
 of  
 the  
 Surveyor

Engine Steam  
 Engine records.

J.P.A.

GET THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.

New York.

Continuation of Report No. 27182 dated 18 Jan. 27 on the

STS "E. T. BEDFORD"

+ NDB.

Two low Water Tube boilers and one Vertical Heating  
 boiler have been fitted as per reports herewith.  
 The safety-values have been adjusted under steam and  
 they are now in good & safe working condition, and  
 eligible in my opinion to receive notation  
 +2 WTD B-12-26 and 1 VHB 12-26 in the Register Book,  
 subject to Annual survey of the Water tube donkey boilers

J. Mac Watt

Marks on low Tail shafts

LLOYD'S #4856 15-10-25 JMB  
 LLOYD'S #4855 15-10-25 JMB.  
 LLOYD'S #4857. 15-10-25. JMB. Spare.

Intermediate Shafting.

LLOYD'S 4859. 15-10-25 JMB.  
 LLOYD'S 4858 15-10-25 J.M.B.



© 2021

Lloyd's Register  
 Foundation