

Ship Surveyor

Received from Chief Ship Surveyor

"SOUTHERN VENTURER"

REPORT

Nwc.

No. 111890

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

Endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points noted in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

There is an Endorsement of class (B).

The NEWCASTLE Surveyors report this ship placed in drydock and minor repairs effected.

Alterations have been effected at this time including ~~the~~ increase in breadth of the rudder; alterations to No.1 wing tank (p & s), and the fitting of aviation spirit tank under the skidway deck also the fitting of flight deck and hanger in accordance with approved plans.

The Endorsement of Class (B) items continue efficient.

IT IS SUBMITTED the ship is eligible to have record of docking 10,54 assigned as recommended.

10,54 Shl.

~~ENDORSEMENT OF CLASS (B).~~

~~Indents in shell plating (n & s).~~



© 2020

Lloyd's Register
Foundation

009232 - 009234 - 0088

CBM
5-11-54