

REPAIRS, OR EXAMINATION AS PER RULE, FOR

CONDITION SURVEY

NOW DONE:- Vessel placed in dry dock. Hull, bottom, stern frame and rudd
found or now placed and cond

Decks

ndlass, st

d cond

DISC
SECT

384

20110000000

"YAHIKO MARU"

35002

In 1941/42 R.B.

The clearing Committee gave instructions on 12th June, 1942
for the class of this ship, which vessel to be omitted

PRESENT

Decks
Caulking of
Coamings
Beams & Fastenings
Outside Plating
" " in way of sidelights
Breasthooks
Transoms
Frames **Good**
Reverse Frames
Longitudinals
Transverses
Floors
Keelsons
Stringers
Inner Bottom Plating

Bu
Ceiling
Cement or A
(State
Rudder
Steering
Windla
Have
cient
Have Sl
efficient
Have Watertig
efficient ?
Have Ventilators and their Coaming
and found efficient ?

Yes.

ditto
ditto

(State if examined.)

General Observations

Opinion as to

D

St

009341-009349-0139



© 2021

Lloyd's Register
Foundation