

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 30 March 1925 When handed in at Local Office 31 March 1925 Port of Queenstown

No. in Reg. Book 70432 Survey held at Limerick Date, First Survey 24 March Last Survey 25 March 1925

70432 on the Wood, Iron or Steel &c. Garryowen II Master.

TONNAGE:-

GROSS 468⁸

UNDER DECK 468

NET 194

Built at Greenock

Owners J. Bannatyne & Sons, Ltd.

Owners' Address

(if not already recorded in Appendix to Register Book).

By whom J. Brown & Co.

Port belonging to Limerick.

Managers

Destined Voyage River Shannon

Surveyed Afloat or in Dry Dock? Afloat Name of Dock

WB=Cell DBorDBa feet; uE&B feet; f feet; }
total capacity tons. FPT tons; APT tons; MT feet tons. }

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 3814 Port QNS.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER.
* for Special Survey.
Date of last Survey and of Periodical Surveys.

Machinery and Boiler Surveys (including date of N.B., if any).

For towing purposes 1,25

Tail shaft CL 1,25

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined. Not required.

Was a damage report made by anyone else? If so, by whom? No one else.

REPAIRS, OR EXAMINATION AS PER RULE, FOR completion of Special Survey N°1.

Hold and after peak cleared, loose flooring plates in Hold (occupied by Elevator machinery) lifted as required—some at the bilges—bilges and limbers in these parts and in the Engine & Boiler space cleaned out, framing and both surfaces of plating exposed, cleaned and examined and recoated as required. Cement (to above the upper edges of the floors throughout the Hold) carefully inspected, tested by hammering and found sound and adhering satisfactorily to the steel. After peak tank and forward deep tank (next abaft the fore peak bulkhead) cleaned out and examined internally and tested by a head of water 8ft above the crowns of the tanks. Deck examined. Signal mast & rigging examined. Anchors and general equipment examined. Basings and companionways etc. around openings in deck examined (there are no ordinary hatchways and hatch covers). Ventilator coamings and covers examined. Windlass, pumps, watertight door (tried) and air and sounding pipes examined.

SUMMARY OF DAMAGE REPAIRS:-

Renewed ...

Removed and Faird or Repaired ...

Faird or Repaired in place ...

PRESENT CONDITION OF THE

Decks

Caulking of Decks

Waterways

Coamings

Beams & Fastenings

Outside Plating

Caulking of ditto

Rivets

Breasthooks & Crutches

Transoms

Frames

Reverse Frames

Floors

Keelsons

Stringers

Inner Bottom Plating

Plates.

Frames.

R. Frames.

Floors.

Beams.

Str. Plates.

Dk. Plates.

Other Items:-

State if Tanks have been examined inside

State if Tanks now tested

Bulkheads

Ceiling Flooring plates

Cement or Asphalt

(State which.)

Rudder

Steering gear and its connections

Windlass

Have Pumps now been examined and found efficient?

Have Sluice Valves now been examined and found efficient?

Have Watertight Doors now been examined and found efficient?

Have Ventilators and their Coamings been examined and found efficient?

Dblng. Plates under Sounding Pipes

Engine Room Skylights

Coal Bunkers, Open'gs, Lids, &c.

Scuppers

Cargo Hatchways Casings etc.

Hatches

Planking of Wood Vessels

Caulking

Treennails

Breasthooks & Stenson

Transoms, Pointers, & Crutches ditto

Timbers of Frame at openings ditto

Ditto ditto at other places ditto

Stringers, Clamps & Shells ditto

Salting

(State if examined.

Copper, or Y.M. of Wood Vessels

(State if on Belt.)

When put on, Month

Year

Boats

Masts, Yards, &c.

Condition, how ascertained

(State if wedges removed)

Sails

Equipment letter

Anchors, No. of

Cables (State if now ranged)

" length

(on board)

" Rule length

Hawser & Warps

Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptND15, &c."

In my opinion this Vessel is in good and efficient condition and worthy to remain as classed in the Register Book and to have fresh record of survey "Lim 3,25" and notation of "S.S. Lim N°1-25" made therein subject to repairs of damage mentioned above being effected at the Owners' convenience

Survey Fee (per Section 29) £ 7 : 0 : 0

Special Damage or Repair Fee (if any) £ :

Travelling Expenses (if chargeable) £ 3 : 12 : 6

Second Surveyor's Fee (if any) £ :

Committee's Minute

Character Assigned

Fees applied for,

26 March 1925

Received by me,

30 March 1925

£10/12-6 pmd.

Herbert N. Dove

Surveyor to Lloyd's Register of Shipping.

TUES. 8 MAR 1925

TUES. 7 APR 1925

A 1 Subject

For Tow: pumps

S.S. No. 1-25 + Lm.C. 12, 24

© 2021

Lloyd's Register Foundation

Herbert N. Dove

Lloyd's Register
Foundation