

2m,7,26.

Received by Chief Ship Surveyor \_\_\_\_\_

Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME Stl. Sc. K. "ESTRELLA DO NORTE" Rpt. \_\_\_\_\_ Gms. \_\_\_\_\_ No. 15077

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*)

Nature of Survey \_\_\_\_\_

The class of this vessel is subject to indented plating on starboard bow being dealt with at the Owners' convenience.

The Grimsby Surveyors now report the vessel placed on a slipway, bottom cleaned and coated.

The indented plating has been examined and found efficient and in the Surveyors' opinion, need not be dealt with.

It is submitted the vessel appears worthy to remain as classed with record of survey 10-26, without special condition as recommended.

100 A1  
Stm Trawler } Without  
10.26 Edms



© 2021

Lloyd's Register  
Foundation

1.11.26.

009459-009468-0384