

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 16/8/1940 When handed in at Local Office 17 Aug 1940 Port of Kobe.
 No. in Survey held at Innoshima. Date, First Survey 29/7/40. Last Survey 15/8/1940.
 Reg. Book. (No. of Visits FOUR.)
29090 on the Wood, Iron or Steel T.S.S. "MANSEI MARU".
 TONNAGE— Built at Osaka. By whom Osaka Iron Works, Ltd. When 1919 4
 GROSS 7770 Owners Yamashita Kisen Kabushiki Kaisha Owners' Address
 UNDER DK. 7329 Managers Port belonging to Osaka.
 NET 4823

Surveyed Afloat or in Dry Dock? Both Name of Dock Innoshima Dock. Destined Voyage

WB=Cell DBorDBa feet; uE&B feet; f feet
 total capacity tons. FPT tons; APT tons; MT feet tons.
 N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

ist Report, No. 6748 Port Yka

Medical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarized in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

PAIRS, OR EXAMINATION AS PER RULE, FOR CONDITION SURVEY

NOW DONE:- Vessel placed in dry dock. Bottom, stern frame & rudder (lifted) cleaned, examined, found or now placed in good condition and recoated.

Decks, hatchways, hatches and supports, vents and coamings, windlass, steering engine connections and equipment generally examined and found or now placed in good condition.
 Plating in way of ash shoots examined and found in good condition.

PAIRS DUE TO WEAR AND TEAR:-

The following repairs have been carried out at the Owners' request.

1 shell plate in 5th strake below upper deck sheer strake in way of No.2 hold, starboard e - renewed.
 (P.T.O.).

DESCRIPTION OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—	
Renewed									
Removed and Fairred or Repaired									
Fairred or Repaired in place									
GENERAL CONDITION OF THE									
Good	State if Tanks have been examined inside			--	Air and Sounding Pipes			--	
"	State if Tanks now tested			--	Dbng. Plates under Sounding Pipes			--	
"	Bulkheads			--	Engine Room Skylights			Good	
"	Ceiling			--	Coal Bunkers, Open'gs, Lids, &c.			--	
"	Cement or Asphalt (State which.)			--	Oil Bunkers			--	
--	Rudder			Good	Scuppers			--	
--	Steering gear and its connections			"	Cargo Hatchways			Good	
--	Windlass			"	Hatches			"	
--	Have pumps now been examined and found efficient?			--	Planking of Wood Vessels			--	
--	Have Sluice Valves now been examined and found efficient?			--	Caulking ditto			--	
--	Have Watertight Doors now been examined and found efficient?			--	Treenails ditto			--	
--	Have Ventilators and their Coamings been examined and found efficient?			--	Breasthooks & Stemson ditto			--	
--	Yes.			--	Transoms Pointers, & Crutches ditto			--	
--				--	Timbers of Frame at openings ditto			--	
--				--	Ditto Ditto at other places ditto			--	
--				--	Stringers, Clamps & Shells ditto			--	
--				--	Salting ditto			--	
--				--	(State if examined.)			--	
Copper, or Y.M. of Wood Vessels									--
(State if on Felt).									--
When put on, Month									-- Year--
Boats									Good
Masts, Yards, &c.									"
Condition, how ascertained									From deck.
(State if wedges removed)									--
Sails									--
Equipment letter									bt
Anchors, No. of									3B. 1s. 1k.
Chain Locker									--
Cables (State if now ranged)									No
length. mean diam.									stated complete.
(on board)									--
Rule length									300 fms. size 2-6/
Hawser & Warps									--
Standing and Running Rigging									--

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c."

This vessel, so far as now seen, is in good condition and eligible, in my opinion, to be continued as classed with fresh record of survey 8,40.

Survey Fee (per Section 29) Yen 115:00
 Special Damage or Repair Fee (if any) —
 Travelling Expenses (if chargeable) Yen 59:00
 (Including Machinery).
 Second Surveyor's Fee (if any) —

Fees applied for, 15/8/1940

Received by me, 19

Surveyor to Lloyd's Register of Shipping.


Committee's Minute

FRI. 11 OCT 1940

Character Assigned

100 A1
S(P) 7.40

Awng. dk with 2nd
+ Lmc 8.40



Lloyd's Register
 Foundation

009469-009480-0156

1 shell plate in 3rd strake below upper deck sheer strake in way of No.3 Hold-
port side - renewed.

1 Shell plate in 5th strake below upper deck sheer strake in way of No.4 Hold-
starboard side - renewed.

1 Shell plate in 4th strake below upper deck sheer strake in way of No.5 Hold-
starboard side - renewed.

1 Upper deck plate and 1 stringer plate abreast No.1 hatch, port side - renewed.

1 Upper deck stringer plate abreast No.1 hatch, port side - partly renewed.

6 upper deck plates between Nos.1 & 2 hatches.-- renewed.

2 upper deck stringer plates abreast No.7 hatch, starboard side - renewed.

2 stringer plates and 6 deck plates in 2nd deck bunker space, port and starboard sides - renewed.

Hatch coaming horizontal stiffeners at No.4 hatch, port and starboard sides
and No.7 hatch, port side - renewed.

110 wooden hatchboards - supplied.

Other minor repairs carried out. M.A

When Anchors or Cables are supplied, the particulars are to be reported in the following form:—

ANCHORS.

[illegible]

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

CHAIN CABLES.

[illegible]

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.