

ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

Class is Subject to No 5 boiler not being used until the main stop
valve chest has been renewed & the repairs to back end plate
Specially examined under Steam

Chief Surveyors

'S NAME

Mont-Calm

Received from Chief Surveyors

Report

Gls.

No. 61916

For the ~~CHIEF SURVEYOR~~ and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Survey

No 5 boiler stop valve chest renewed When due

Subject to No 5 boiler not being used until the repairs to
back end plate have been examined under Steam
Without special condition re stop valve chest

Noted

Ham

24.1.40

Sp. note in R.L.:- Test stop pipes at B.O.T. survey.

009522-009526-0075



© 2021

Lloyd's Register
Foundation