

REPORT OF SURVEY FOR REPAIRS, &c.

No. in Reg. Book. 17948  
Survey held at on the Wood, Iron or Steel S. Tug TAURUS  
Built at Selly By whom Cochrane & Sons Ltd. When 1945 MONTH 8  
GROSS 292  
UNDER DK. 262  
NET  
Owners Soc. Ann Riniorchiatari  
Managers Riniorchiatari  
Owners' Address  
Port belonging to Venice  
Destined Voyage

Surveyed Afloat or in Dry Dock? Name of Dock  
Cell DB or DBa feet; uE & B feet; f feet  
total capacity tons. FPT tons; APT tons; MT feet tons.  
Only alterations in the existing records of tanks should be inserted.  
N.B. All alterations in the existing records should be underlined.  
Last Report, No. 19694 Port SOU  
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)  
CHARACTER: \* for Special Survey Date of last Survey and of Periodical Surveys  
Machinery and Boiler Surveys (Including date of N.B., if any)  
+10021 LMC (R) 845  
for towing Services  
3.49 TS 3.49 06  
Fitted for oil fuel 8.45 ft above 150 ft.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined  
Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins.  
Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS :-

	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed ...								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place ...								

PRESENT CONDITION OF THE

Decks	Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Felt.)
Caulking of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year
Coamings	Cement or Asphalt	Oil Bunkers	Boats
Beams & Fastenings	Rudder	Scuppers	Masts, Yards, &c.
Outside Plating	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained (State if wedges removed.)
" " in way of sidelights	Windlass	Hatches	Equipment letter
Frames	Have pumps been examined and found efficient?	Planking	Ancors, No. of
Reverse Frames	Have Sluice Valves been examined and found efficient?	Caulking	Cables (State if now ranged)
Longitudinals	Have Watertight Doors been examined and found efficient?	Treenails	" length mean diamr. (on board.)
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stimson	" Rule length size
Floors	Air and Sounding Pipes	Transoms, Pointers & Crutches	Chain Locker
Keelsons	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Hawsers & Warps
Stringers		" " at other places	Standing and Running Rigging
Inner Bottom Plating		Stringers, Clamps & Shelves	Sails
Have the Tanks been examined internally?		Salting	
Have the Tanks been tested?		State if examined.	

General Observations, Opinion as to Class, Recommendation, &c. :-  
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example: "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Survey Fee (per Section 29) £  
Special Damage or Repair Fee (if any) (per Sec. 29) £  
Travelling Expenses (if chargeable) £  
Second Surveyor's Fee (if any) £  
Committee's Minute  
Fees applied for, 19  
Received by me, 19