





in good condition.

Propeller (solid bronze) 3 blades bent at tips, faired and dressed.

One (1) blade piece missing, approximately 3 in. deep, 4 in. long, approximately 36 in. from tip on backing edge, built up by welded, dressed in way, it was stated by Owners representative that a new propeller has been ordered from the makers and will be fitted next docking.

Machinery generally examined and found well maintained.

Pumping arrangements and electrical equipment generally examined and tried out under working conditions and found satisfactory.

Main & Auxiliary machinery tried out for 2 hours and under manouvering conditions and found satisfactory.

Spare tail shaft placed on board, stamed as follows:-

F.B. Co. 7048 heat No.85 S. 461 - A1

Ser.160 W. AB62 JSC 11-8-46

AB 118 HC 12-16-46

The following can be credited to LMC.

Seacocks and valves

2 Main boilers examined throughout and safety valves adjusted.

Tailshaft drawn and examined.



© 2021

Lloyd's Register  
Foundation