

Rpt. 8

Port SINGAPORE. 24 NOV 1961

No. 15790

Date of writing Report 14-11-61.

When handed in at Local Office

Received London

Survey held at SINGAPORE.

No. of Visits One

First Date and 19

Last Date 1/11/ 19 61.

REPORT OF SHIP SURVEYS AND REPAIRS

(The Surveyor's attention is drawn to the relevant requirements of Chapters B & C of the Rules.)

No. in R.B.

30453

on the Iron or Steel M.S.

"SENAI"

Tons gross 522

Year Month

When 1945 - 6

Built at HESSLE.

By Whom HENRY SCARR LTD.

Owners STRAITS S.S. CO. LTD.

Owners' address
(If not already in R.B.)

Managers

Port of Registry SINGAPORE.

Surveyed Afloat or in Drydock on Slipway. Name of Dock Singapore Slipway.

Date of last examn. in Drydock 1/11/61.

N.B.—Any alterations in existing particulars in the Register Book should be reported and underlined.

Last Report: No.

To be filled in at Head Office.

Port

Particulars of Classification (which must be inserted precisely as in Register Book and Supplement)

Surveys must be reported in the terms of the Rules. The nature and extent of Examinations and Repairs (if any) must be stated in detail, the parts examined and their condition being clearly indicated. For Annual, Special or other Condition Surveys the Summary of Examination and Condition on the back of the Report is to be carefully completed and amplified if necessary in the body of the Report. Outstanding items to complete the Survey should be summarised at the end of the Report. The reasons for Repairs must be stated. Repairs on account of Damage (the alleged cause of which must be stated) should be separated from Repairs due to other causes, and, besides being detailed in the body of the Report, should be summarised in the form below. When, at a Special Survey, the Shell and Deck Plating is drilled the results must be reported on Report 8(Dr). Whenever Anchors or Chain Cables are replaced or retested the necessary particulars are to be given on Report 8(Eq) which is to be attached to this Report.

Give dates and references to any letters relating to this Report

SHIP'S CLASS		Machinery	
Date of Special and of Drydocking Surveys, etc.			
BS* with freeboard.		MBS	CS 4/58
Dkg.	12/60	TSOG	12/60
SS	4/58		

EW

In damage cases where the Surveyor has not made a special damage report he should state whether he offered

his services for this purpose and to whom and why they were declined

Freeboard as marked on ship and now verified ft ins

Was a damage report made by anyone else? If so, by whom?

EXAMINATION AND REPAIRS AS PER RULE FOR ANNUAL DOCKING.

W & T REPAIRS

Chine bar under fore foot deeply pitted at several places, now reinstated by electric welding.

S.R.L. Item

"Indented port side shell plate C4 (from aft) to be specially examined and dealt with at the next Special Survey".

NOW DONE

Port side shell plate C4 (from aft) examined and found to continue efficient.

CONTINUATION OVER/OR SHEET 2

SUMMARY OF DAMAGE REPAIRS	Shell Plates	Frames	R. Frames	Floors and Bracket Floors	Inner Bottom Plates	Deck Plates	Beams	Other Items
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

Has a Survey also been held on machinery of the Ship? Yes

Is Classification Certificate required? If so, to be sent to No

If so, is the Report sent now, or when will it be sent? Now

Has Interim Certificate been issued? Yes

GENERAL OBSERVATIONS, OPINION AND RECOMMENDATION AS TO CLASS

State clearly what alteration, if any, is suggested to be made in the existing Classification or Survey or other records of the Ship in the Register Book consequent upon this survey; for example:—"to remain as Classed in the Register Book without fresh record of Docking"; "to remain as Classed and to have record of drydocking 1,55"; or "to remain as Classed and to have record of drydocking 1,55, and the notation of S.S. . . . 1,55".

This vessel, so far as now seen is eligible in my opinion to remain as Classed with fresh record of D.S. 11/61 subject as previously recommended to the indented port side shell plate C4 (from aft) being specially examined and dealt with as found necessary at the next Special Survey.

Date of Committee

TUESDAY 12 DEC 1961

Minute

DS 11 61 subject



© 2020

Lloyd's Register Foundation

PARTS OF THE SHIP AS INDICATED BELOW HAVE BEEN EXAMINED FOR.

SURVEY

Have the spaces now surveyed been cleared and cleaned as necessary?..... **Yes**

Have the close ceiling and cargo battens, linings, pipe casings, etc., been removed and replaced as required by the Rules?..... **No**

Have the bilges been cleaned out and examined?..... **No** Has cement in bottom been examined?..... **No**

Has steelwork had rust removed and afterwards been recoated as necessary?..... **Yes**

Were inspection plugs or any insulation removed in insulated spaces for examination of steelwork?..... **No**

Has a Load Line Survey been held?..... **No** If so, state which..... **-**

Have the shell and deck plating been drilled as per Rule?..... **No** If so, Report 8(Dr) to be attached..... **-**

Have any alterations to the approved scantlings and arrangements now been effected?..... **No** If so, report details in body of Report.

NOTE:—Indicate which compartments and/or tanks have been examined or tested by giving the identification numbers and inserting the word "Yes", e.g. Holds: Nos. 1, 2 & 3—Yes; or All—Yes.

The present condition of the following parts in so far as examined is to be reported:—

Have conditions (A) or endorsements (B) of Class (if any) been dealt with? See Below

REMARKS, REPAIRS, Etc. (Contd.)

Second Surveyor's Fee (if any)

Date when Alc. Rendered

5-1

© 2020

Surveyor's Fee (if any)
 n A/c. Rendered
 Date 10/11/69