

Now done:- Compass repaired and refitted. Steering chains shortened two links

SPECIAL NOTE.

One main engine to ex. annually as alternative
to bs (Lr 104128)



© 2020

Lloyd's Register
Foundation

009674-009681-0239

Transverses.....

efficient?.....

Have Watertight Doors now been examined and found

Transoms Pointers, & Crutches ditto.....

Timbers of Frame at openings ditto.....

Cables

"