

4 E

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

EL'S NAME

"NEW DAGENHAM".

Rpt.

Lis.

No.

2867

remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/92.)

of Survey

REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH GROUNDING AND


HEAVY WEATHER.

Starboard screw shaft examined and both propellers changed.

A cylinder cover renewed; electric fittings overhauled and minor repairs.

It is submitted the vessel is eligible to remain as classed with fresh record of survey Starboard S 1,38

Note part Engine Survey.



© 2020

Lloyd's Register
Foundation

18.2.38.

009674-009681-0243

Opinion and Recommendation:—