

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

4 E

135.

ed by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

EL'S NAME "NEW DAGENHAM".

Rpt. Bdx. No. 4979.

remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH GROUNDING.

e of Survey

Starboard screw shaft examined and both propellers renewed.

Main clutches of the auxiliary engine examined.

It is submitted the vessel is eligible to remain as classed with fresh record of survey Starboard S 1,38.

Note part Engine Survey.



© 2020

Lloyd's Register Foundation

1.2.38.

009674-009681-0248

can to continue her consumption voyage to signat.