


It is submitted the Dundee Surveyors should be requested to state specifically how many rivets were found by them to be defective in the engine seating of the S.S. "LONDON QUEEN" and to give in detail what the other defects, if any, were which led to the engine seating being rebuilt and re-riveted.

A.



009702-009710-0046

sterdam, and