

When received in London Office

0g " _____ " _____

Special No. _____ No. in Reg. Book _____ BEAM.

i or Steel *Steel* State whether Classed by Lloyd's Register *+ 100 A1*

I have to report that the Freeboard from the centre of disc to the top of the

Committee to this vessel have been correctly marked on the vessel's sides,

_____ ft. 5 ins. ✓

From centre of disc to top of statutory deck line)	ft	ins
1		
2		
3		
4		
5		
6		
7		
8		
9		
10		
11		
12		
13		
14		
15		
16		
17		
18		
19		
20		
21		
22		
23		
24		
25		
26		
27		
28		
29		
30		
31		
32		
33		
34		
35		
36		
37		
38		
39		
40		
41		
42		
43		
44		
45		
46		
47		
48		
49		
50		
51		
52		
53		
54		
55		
56		
57		
58		
59		
60		
61		
62		
63		
64		
65		
66		
67		
68		
69		
70		
71		
72		
73		
74		
75		
76		
77		
78		
79		
80		
81		
82		
83		
84		
85		
86		
87		
88		
89		
90		
91		
92		
93		
94		
95		
96		
97		
98		
99		
100		

Fresh water line above centre of disc . . . 42 ins. ✓

Indian Summer line above centre of disc . . .

Winter line below centre of disc

Winter North Atlantic line below centre of disc

Distance between the top of hatchway deck line on vessel's side and the intersection of the vertical line at main, spar or upper dk.

NOTE.—It should be clearly shown whether the statutory deck line is set on from a wood or iron line.

The openings in front of long poops are closed full length

Ch Brown Surveyor.

Statement No. 20126 Date of Committee's Minute 13.8.09

18 ft 6 ins.

Shoulded Depth for record 17.00

boards compared and found correct by J.M. date 11.9.07

fee paid? *Yes* Form for Certificate *10/25/2020*

Instructions *Write Certificate of 1946.* date *1/1/49* *Hold's Register*

rtificate written 11-9-09 Noted for posting

Foundation

009702-009710-0290

WINTER LINE BELOW " " ... *March 1906.* 3 ...