

Carrying Petroleum in Bulk.
m.v. "DIRECTOR MADARIAGA"
Rotterdam Rpt. No. 32583.

The lighting fittings installed in the bridge 'tween deck do not comply fully with the Rule requirements for flameproof enclosure, notably in respect of the provision for cable entry. The rubber bushes used in the fittings in question are likely to deteriorate with age but could be considered effective for a limited period.

IT IS ACCORDINGLY SUBMITTED the vessel's class be made subject to the lighting fittings in the bridge 'tween deck being replaced by approved fittings before 31st December, 1951.

IT IS FURTHER SUBMITTED the Rotterdam Surveyors be informed that it is noted that no reference has been made in their Rpt. 13 to the fact that the flameproof lighting fittings in the bridge 'tween deck did not comply with the Rules. In this connection, their attention might be directed to the Secretary's letter of the 16th March last and subsequent correspondence concerning the fittings in question and the Surveyors requested to state why these fittings have been accepted by them for installation in the vessel under notice.

S.A.

9th November, 1950.

BOW



© 2021

Lloyd's Register
Foundation

009790-009788-0285

2 Air Compressors, No. 2. ✓ No. of stages 2 Diameters 230/212 Stroke 160 mm
2 Air Compressors No. 2 No. of stages 2 Diameters 230/212 Stroke 160 mm