

Has a
17 80, 10
+ bow chocks renewed. 6. Deck renewed forward & caulked throughout. 7. Hatch

2m.1.20.

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

29 SEP 1920

VESSEL'S NAME _____ Wood S.S. "STARLIGHT". _____ Rpt. _____ Abn. _____ No12558

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22.)

Nature of Survey _____

Condition -

The Aberdeen Surveyors report this vessel examined on a slipway and repairs effected to outside planking, deck etc. on account of damage sustained while on Government Service.

The necessary reconditioning alterations have also been effected.

It is submitted the vessel appears worthy to remain as classed with record of survey 9.20, as recommended.

11 A1 For fishing purposes.
9.20 Abn.



© 2004

28. 9. 20.
Lloyd's Register
Foundation

009827 - 009838 - 0136

J. Richardson

(per Sec. 20)

Travelling Expenses (if chargeable) _____ 2

Received by me,

18/9/20 19.20