

(Received at London Office 9 FEB 1951)

No. 241

REPORT OF SURVEY FOR REPAIRS, &c.

ing Report 22nd Jan. 1951 When handed in at Local Office 19... Port of KOBE
Survey held at Shimonoseki Date, First Survey 22nd Aug. Last Survey 12-Sept. 1950
on the Wood, Iron or Steel Single Screw Steamer "BUNYO MARU" (No. of Visits 6)

Built at Nagasaki By whom Kawaminami Industry Co. Ltd. YEAR 1949 MONTH 8
Owners Toyo Kisen K.K. Owners' Address Tokyo
Managers (If not already recorded in Appendix to Register Book)
Port belonging to Tokyo

Afloat or in Dry Dock? Both Name of Dock Shimonoseki S.Y. Destined Voyage
DBA feet; uE & B feet; f feet
acity tons. FPT tons; APT tons; MT feet tons.
All alterations in the existing records should be underlined.

Report, No. Port
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)
CHARACTER: * for Special Survey. Date of last Survey and of Periodical Surveys.
Machinery and Boiler Surveys (Including date of N.B., if any).
Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins.
Was a damage report made by anyone else? if so, by whom?

OR EXAMINATION AS PER RULE, FOR Classification.
Rule's requirements for Classification of "Ships Not Built Under Survey" have now been
ed with as follows:-
ne:- Vessel placed in drydock, bottom and rudder, cleaned, examined and recoated.
d:- All holds, tween decks, Fore and aft peak spaces, cross bunker, Engine and boiler spaces,
plating in way of side lights, decks, hatchways with covers, supports, tarpaulins, cleats
and battening arrangements, anchors, chain cables, chain lockers, masts, rigging,
steering gear and auxiliary gear, windlass, general equipment pumps, W/T doors, ventilators,
coamings and covers, air and sounding pipes, casings, cargo battens, boats.

onal Freeboard assigned, cut in ship's sides and verified.
internally and tested:- Fore and aft peaks, all double bottom tanks. P.T.O.
DAMAGE REPAIRS:- Shell Plates. Frames. R. Frames. Floors and Bracket Floors. Beams. Inner Bottom Plates. Dk. Plates. Other Items:-
and Fairled or Repaired
Repaired in place

DITION OF THE
Good Bulkheads Good Ceiling Cement or Asphalt Rudder (Lifted) Steering gear and its connections. Windlass Have pumps been examined and found efficient? Yes Have Sluice Valves been examined and found efficient? Yes Have Watertight Doors been examined and found efficient? Yes Have Ventilators and their Coamings been examined and found efficient? Yes Air and Sounding Pipes Doubling Plates under Sounding Pipes Good
Engine Room Skylights Coal Bunkers, Openings, Covers, &c. Oil Bunkers Scuppers Cargo Hatchways Hatches Planking Caulking Treennails Breasthooks & Stemson Transoms, Pointers & Crutches Timbers of Frame at openings " " at other places Stringers, Clamps & Shelves Salting State if examined.
Copper, or Y.M. (State if on Felt.) When fitted, Month Year Boats Good Masts, Yards, &c. Condition, how ascertained (State if wedges removed.) Equipment letter W Anchors, No. of 3B 1S Cables (State if now ranged) See 1st Entry Rpt. length mean diam. Rule length size Chain Locker Good Hawsers & Warps Standing and Running Rigging Sails

Observations, Opinion as to Class, Recommendation, &c.:-
e clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon
ed) at, thus, for example:- "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of
3," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."
Length 7.50, and Classed 9.50 S.S. Shimonoseki
Submitted this vessel be recommended to the Committee for the Class 100A1, with record

See Hull 1st Entry, Rpt. Fees applied for, Repair Fee (if any) Received by me, (if chargeable) Fee (if any)
Signature of Surveyor to Lloyd's Register of Shipping

TUES. 25 SEP 1951
Signed See minute on F.E. Rpt. Vol. 241
Lloyd's Register Foundation
009860-009868-0232

It must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

This image shows a blank, aged, cream-colored page, likely an endpaper or flyleaf of a book. The paper has a slightly textured appearance with some faint smudges and discoloration, characteristic of old paper. The left edge of the page shows the binding of the book.

must be taken that the cor

must be taken that

must be taken

This image shows a blank, aged, cream-colored page, likely an endpaper or flyleaf of a book. The paper has a slightly textured appearance with some faint smudges and discoloration, characteristic of old paper. The left edge of the page shows the binding of the book.

This image shows a blank, aged, cream-colored page, likely an endpaper or flyleaf of a book. The paper has a slightly textured appearance with some faint smudges and discoloration, characteristic of old paper. The left edge of the page shows the binding of the book. There is no text or other markings on the page.

This image shows a blank, aged, cream-colored page, likely an endpaper or flyleaf of a book. The paper has a slightly textured appearance with some faint smudges and discoloration, characteristic of old paper. There is no text or other markings on the page.