

" MARLEEN " Ottawa Maycliff

Service Limits for this vessel have
been received.

Awaiting Amsterdam reports —
re fitting of $2\frac{1}{2}$ hatch covers & reverse
frames, before vessel is classed.

14/1/47

009879-009887-0017