

A test cock is fitted to the oil fuel settling tanks and is of the self-closing type.
Heating coils(solid drawn steel) are fitted to all tanks containing oil fuel and the exhaust drains are led to an observation tank.
The heating coils were tested as per Rules.
A thermometer pocket is fitted to the settling tanks.
The oil fuel pumps can be controlled from the deck in the event of emergency.
A water service pipe is fitted to stokehold and a hose is fitted to supply water in the event of fire.
Perforated steam pipes are fitted under the boilers and oil fuel units and were seen working with control from deck.
Sand in boxes has also been supplied to the boiler room.
All wood fittings and bearers were removed from the boiler room.
Savealls are fitted to all furnace mouths.
All lead suction pipes have been removed from the boiler room.
The funnel damper has been removed.
3 electric lights have been fitted above the tank tops(watertight fittings) under the boilers.
The above installation has been completed as per amended plans, examined, tested under working conditions and found in order.

Boiler Survey.

Now done:

The two main boilers were examined internally and externally together with superheaters and monitors and the safety valves adjusted under steam.
The oil fuel installation was examined under working conditions and found in order.
The fire extinguishing apparatus was tried and found in order.

Repairs now effected:

Minor repairs only.



© 2021

Lloyd's Register
Foundation