

No. in Reg. Book. 201300n the Wood, Iron or Steel

Survey held at Sc. Sn. "EMIL R. AN"

Date, First Survey

Last Survey 19

TONNAGE:-

GROSS 1223

UNDER DK. 865

NET 711

Built at Middlesbrough

By whom W. Harland & Son

When 1901 11

Owners A. Stala Rederi Aktief (S. Enkoring)

Managers

Port belonging to Stockholm

Surveyed Afloat or in Dry Dock? WB=CellDBorDBa

Name of Dock

Destined Voyage

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.

Years Assigned now or previously.

Machinery and Boiler Surveys (including date of N.B., if any).

100 A1 4.31

ss Hbg. 2nd

NB 3-4.27

LMC 4.27

BS. 6.31

CLN 6.30

Cargo battens not fitted

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 986 Port Dnz

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Society's Freeboard (if assigned) as painted on Ship and now verified

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

UNDECKING CASE

DISCLOSED SECTION No. 674

SUMMARY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :-
Renewed								
Removed and Faird or Repaired								
Faird or Repaired in place								

Decks	State if Tanks have been examined inside	Dblng. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels (State if on Felt)
Caulking of Decks	State if Tanks now tested	Engine Room Skylights	When put on, Month Year
Coamings	Bulkheads	Coal Bunkers, Open'gs, Lids, &c.	Boats
Beams & Fastenings	Ceiling	Scuppers	Masts, Yards, &c.
Outside Plating	Cement or Asphalt (State which.)	Cargo Hatchways	Condition, how ascertained (State if wedges removed)
Breasthooks	Rudder	Hatches	Sails
Transoms	Steering gear and its connections	Planking of Wood Vessels	Equipment letter
Frames	Windlass	Caulking ditto	anchors, No. of
Reverse Frames	Have Pumps now been examined and found efficient?	Treenails ditto	Cables (State if now ranged)
Longitudinals	Have Sluice Valves now been examined and found efficient?	Breasthooks & Stemson ditto	length size (on board)
Transverses	Have Watertight Doors now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Rule length size
Floors	Have Ventilators and their Coamings been examined and found efficient?	Timbers of Frame at openings ditto	Hawser & Warps
Keelsons		Ditto Ditto at other places ditto	Standing and Running Rigging
Stringers		Stringers, Clamps & Shelves ditto	
Inner Bottom Plating		Salting ditto (State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c."

Survey Fee (per Section 29)

Special Damage or Repair Fee (if any) (per Sec. 29)

Travelling Expenses (if chargeable)

Second Surveyor's Fee (if any)

Fees applied for, 19

Received by me, 19

Surveyor to Lloyd's Register of Shipping.

Committee's Minute

TUE. 19 APR 1932

Withdraw class

insert ("")

21/4/32

Special General Committee

Thursday, 21st April, 1932

Classing Committee's decision confirmed

Lloyd's Register Foundation

NOTED FOR PORTING

009912-009919-0055