

DISCLASSIFIED Pt. 8.
SECTION
No. 609

(Received at London Office)

Lon No. 129139

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of...
No. in Reg. Book 72616 Survey held at on the Wood, Iron or Steel MV OTIS Date, First Survey Last Survey 19...
(No. of Visits)

Built at Hamburg By whom Deutsche Werft A.G. When 1936 MONTH 11
Owners Petrosinis Petrol Soc Anon Owners' Address
Managers Port belonging to Venice

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage
Cell DBor DBa feet: uE&B feet: f feet }
total capacity tons. FPT tons; APT tons; MT feet tons. }

only alterations in the existing records of tanks should be inserted.
N.B.—All alterations in the existing records should be underlined.

Last Report, No. 14983 Port Tr

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
CHARACTER. & for Special Survey. Date of last Survey and of Periodical Surveys. Machinery and Boiler Surveys (Including date of N.B., if any).
+100A1 5,54 +LMC 12,50
SS HAV 4,50 DBS 5,54
+NE 12,50
TSCL 1,53
Carrying petroleum in bulk
Oil Eng

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.
Society's Freeboard (if assigned) as painted on Ship and now verified OIL ENGINES ins.
CONTINUOUS SURVEY

Was a damage report made by anyone else? if so, by whom?
REPAIRS, OR EXAMINATION AS PER RULE FOR

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors.	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed ...								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place ..								

PRESENT CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or Y.M.
Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	(State if on Felt.)
Planking of Decks	Cement or Asphalt	Oil Bunkers	When fitted, Month Year
Stowings	Rudder	Scuppers	Boats
Stowings & Fastenings	Steering gear and its connections	Cargo Hatchways	Masts, Yards, &c.
Outside Plating	Windlass	Hatches	Condition, how ascertained
" " in way of sidelights	Have pumps been examined and found efficient?	Planking	(State if wedges removed)
Frames	Have Stance Valves been examined and found efficient?	Caulking	Equipment letter
Transverse Frames	Have Watertight Doors been examined and found efficient?	Treenails	Anchor, No. of
Longitudinals	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	Cables (State if now ranged)
Diagonals	Air and Sounding Pipes	Transoms, Pointers & Crutches	" length mean diamr.
Keelsons	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	(on board.)
Stringers		" " at other places	" Rule length size
Inner Bottom Plating		Stringers, Clamps & Shelves	Chain Locker
Have the Tanks been examined internally?		Salting	Hawsers & Warps
Have the Tanks been tested?		State if examined	Standing and Running Rigging
			Sails

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1-38," or "to remain as classed and to have record of survey, 1-38, and the notations of ss No. 1-38."

Survey Fee (per Section 23)	Special Damage Repair Fee (if any) (per Section 23)	Travelling Expenses (if chargeable)	Second Surveyor's Fee (if any)	Committee's Minute	Character Assigned
£	£	£	£		

FRIDAY 17 JUN 1955
Surveyor to Lloyd's Register of Shipping.
GENERAL COMMITTEE
Thursday, 30th June, 1955
Classing Committee's decision confirmed.

MADE AND PRINTED IN ENGLAND.
Transfer Ink.
80m. 1.54
(The Surveyors are requested not to write on or below the space for Committee)

If Certificate required? if so, to be sent to

Lloyd's Register Foundation

009952-009975-1209