

The KIEL Surveyors report (12.50) the vessel placed in dry dock and, due to damage caused by collision, grounding and

009962-009975-0214

Research Dept.

M.V. Elis

A plan in triplicate of the intermediate shaft has been forwarded as requested in Secretary's letter 'E' of 25-1-51.

But it seems that a plan of the screw shaft is still required.

Plan of intermediate shaft noted & in order.  
Plan of screw shaft is 754  
required.  
3.4.51.

The details of the intermediate shaft, as shown on the plan meet the requirements of the Rules.

2-1  
1/9/51.

29/3/51. J.P. Va.