

FRIDAY 27 NOV 1959
 FRIDAY 4 DEC 1959

NOTES
 POSITION

Owners request

bsl

GENERAL COMMITTEE

Thursday,

7th January 1960.

Classing Committee's
 decision confirmed.

A.B.H.

LEAVE THIS SPACE BLANK

Survey fees

Damage fee

Expenses

Date when A/c rendered

Essential Independent Pumps (Identify by position)

33 Bilge, Ballast & Oil Fuel Suction Lines, Fittings & Controls

34 Have the remaining Piping Arrangements & Fittings in the machinery space been examined as considered necessary?

35 Fresh Water Coolers

36 Inb. Oil Coolers

37 Heaters (state service)

38 Independent Air Compressors, Coolers & Safety Devices

39 Air Receivers & Safety devices—Main

40 Auxiliary

41 Oil Fuel Tanks (Not forming part of hull structure)

42 Evaporators

43 Have Evaporator Safety Valves been tested under steam?

44 Steering Machinery

45 Windlases

AUXILIARY ENGINES (Identify by position)

ELECTRICAL EQUIPMENT

PROPULSION

PORT

STARBOARD

AUXILIARY EQUIPMENT

a Generators	1 Generators & Governors
b Exciters	2 Motors
c Air Coolers	3 Switchboards & Fittings
d Motors	4 Circuit Breakers
e Air Coolers	5 Cables
f Control Gear, Cables, etc.	6 Insulation Resistance
g Insulation Resistance	7 Steering Gear Generators and Motors
h Insulating Oil Test	8 Navigation Light Indicators
i Overspeed Governors	
j Magnetic Couplings	
k Air Gap	

BOILERS OPENED UP & EXAMINED (Identify by position and state latest date of internal examination of each boiler)

AUXILIARY, DONKEY or PRESS

Superheaters

Safety Valves

Mountings, Doors & Fastenings

Safety Valves Adjusted to Sat. Spt.

Boiler Securing Arrangements

Main Economisers

Steam Heated Steam Generators

Were Oil Burning System & Remote Controls examined working in accordance with Rules?

Have Saturated Steam Pipes in cylindrical boiler smoke boxes been examined as required by Rules?

EXAMINATION & TESTING OF STEAM PIPES (State material)

Main

Were Copper Pipes annealed?

PARTICULARS OF DEFECTS & REPAIRS, ETC. (Damage repairs should be detailed separate from wear and tear repairs; state what action has been taken regarding items which are subjects of class)

Auxiliary (over 3 in. bore)

Have Saturated Pipes in cylindrical boiler smoke boxes been tested?

Exhaust Gas Heated Economisers

Steam Generator Safety Valves Adjusted to

Forced Circulating Pumps

Funnel

PARTICULARS OF DEFECTS & REPAIRS, ETC. (Damage repairs should be detailed separate from wear and tear repairs; state what action has been taken regarding items which are subjects of class)

© 2021



Lloyd's Register
 Foundation