

Grounding damage - propeller &

N.B. - If this Report is copied by copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

Sea connections examined.

M.S. No 2 due 9.27. partly held on
Engines not advanced.

Due 6.27.

Laid up.

It is submitted that this
vessel WILL BE eligible
for the record. + M.C.M.S. 3.27

When the cylinders
pistons & slide
valves have been
examined.

23/5/28.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2021

Lloyd's Register
Foundation