

Windlass and steering engine opened up and examined.
Valves, pipes, strainers and pumping arrangements examined.
2-40 K.W. generators opened up and examined.
Electric installation examined, megger tested and found in order.
The two main boilers were examined over all parts with doors, mountings and safety valves found in good order. Safety valves adjusted under steam as stated above.
Steam pipes tested as required by the Rules and found tight.
The machinery tried under working condition and found satisfactory.

Repairs,

Minor repairs and adjustment effected.

One new Mn bronze propeller blade (Material test in accordance with the Rule requirements) placed on board as spare at this time.

SRL It was noted that there is no alternative means of supply provided for the navigation lights.
The Owners request that this modification be deferred until November 1950 merits the favourable consideration of the Committee.