

S.S. "KURETAKE MARU"

Repairs due to wear & tear:-

H.P. slide valve renewed.
Ballast pump:- all piston rods and water buckets renewed.
Donkey feed pump:- water cylinder liner renewed.
Fore end plate lower flange corners of Port & Centre Boilers found grooved,
grooves cut out and electrically welded.
Other minor repairs and adjustment effected.

Mh.

Not held.
It is submitted that
this vessel is eligible for
THE RECORD. *File 1140*

RM
8/14

