

should be summarised in the
Plating is drilled the results must be reported on Report 8(Dr). Whenever Anchors or Chain
Cables are replaced or retasted the necessary particulars are to be given on Report 8(Ea)

MEMORANDUM

21 JUL 1959

LLOYD'S REGISTER OF SHIPPING,

71, FENCHURCH STREET,
LONDON, E.C.3.

(Ref. H.)

Surveyor(s) at **RIO DE JANEIRO**

Date: **16 APR 1959**

Name: **S.S. "SANTA BERNADETTE"**

✓ PPR

QUESTION

ANSWER

I shall be glad if you will
certain from the Owners and
let me know what arrangements they
propose making to carry out the
crewshaft Survey which will
come due at the end of June.

Date:— 15th. July, 1959

Owners advise ship will be docked
for survey in Rio, at end of Sep-
tember, 1959.



Mant

CRP



© 2021

Lloyd's Register
Foundation

010219-010228-0119