

Rpt. 8

Port TRINCOMALEE

No. 4988

Date of writing Report 27th September, 1961, When handed in at Local Office

Received London -2. OCT. 1961

Survey held at TRINCOMALEE No. of Visits ONE

First Date 16.9.1961

Last Date 16.9.1961

REPORT OF SHIP SURVEYS AND REPAIRS

The Surveyor's attention is drawn to the relevant requirements of Chapters B & C of the Rules.

No. in R.B.

on the Iron or Steel

BARGE CHEOY LEE YARD NO. 856

Tons gross 114

Built at HONG KONG

By Whom CHEOY LEE SHIPYARD

When 1961

Owners CEYLON MINERAL SANDS CORPORATION.

Owners' address 181 1/2 UNION PLACE, P.O. BOX 1212, COLOMBO 2.

Managers

Port of Registry COLOMBO

Surveyed Afloat or in Drydock Afloat.

Name of Dock

Date of last examn. in Drydock

N.B.—Any alterations in existing particulars in the Register Book should be reported and underlined.

Last Report: No. 16439, Port H.K.

Particulars of Classification (which must be inserted precisely as in Register Book and Supplement)

Surveys must be reported in the terms of the Rules. The nature and extent of Examinations and Repairs (if any) must be stated in detail, the parts examined and their condition being clearly indicated. For Annual, Special or other Condition Surveys the Summary of Examination and Condition on the back of the Report is to be carefully completed and amplified if necessary in the body of the Report. Outstanding items to complete the Survey should be summarised at the end of the Report. The reasons for Repairs must be stated. Repairs on account of Damage (the alleged cause of which must be stated) should be separated from Repairs due to other causes, and, besides being detailed in the body of the Report, should be summarised in the form below. When, at a Special Survey, the Shell and Deck Plating is drilled the results must be reported on Report 8(Dr). Whenever Anchors or Chain Cables are replaced or retested the necessary particulars are to be given on Report 8(Eq) which is to be attached to this Report.

London Letter F/PS 6.9.61

Give dates and references to any letters relating to this Report.

SHIP'S CLASS Date of Special and of Drydocking Surveys, etc.	Machinery
CLASS CONTEMPLATED.	NONE

In damage cases where the Surveyor has not made a special damage report he should state whether he offered

his services for this purpose and to whom and why they were declined.

Freeboard as marked on ship and now verified

ft ins

Was a damage report made by anyone else? If so, by whom?

EXAMINATION AND REPAIRS AS PER RULE FOR GENERAL EXAMINATION.

General Examination afloat now carried out on arrival at Trincomalee after towage from HongKong. All found in good and undamaged condition.

CONTINUATION OVER/OR SHEET 2

SUMMARY OF DAMAGE REPAIRS	Shell Plates	Frames	R. Frames	Floors and Bracket Floors	Inner Bottom Plates	Deck Plates	Beams	Other Items
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

Has a Survey also been held on machinery of the Ship? None.

Is Classification Certificate required? If so, to be sent to Yes, Owners.

If so, is the Report sent now, or when will it be sent?

Has Interim Certificate been issued? Yes.

GENERAL OBSERVATIONS, OPINION AND RECOMMENDATION AS TO CLASS

State clearly what alteration, if any, is suggested to be made in the existing Classification or Survey or other records of the Ship in the Register Book consequent upon this survey; for example:—"to remain as Classed in the Register Book without fresh record of Docking"; "to remain as Classed and to have record of drydocking 1,55"; or "to remain as Classed and to have record of drydocking 1,55, and the notation of S.S. . . . 1,55".

This barge, so far as now seen, is in good condition, and eligible, in my opinion, to be classed +100A "BARGE" For Ceylon Coasting Service.

Surveyor to Lloyd's Register of Shipping

Date of Committee

MONDAY - 6 NOV 1961

Minute

Noted - See Ct minute dated 6.10.61

30m.5.55



© 2021

Lloyd's Register Foundation

010263-010275-0137

DISCLOSED SECTION No. 724

30 OCT 1961

See paragraph of 3.10.61 DMM 21.10.61

TABLE 1

PARTS OF THE SHIP AS INDICATED BELOW HAVE BEEN EXAMINED FOR

SURVEY

Items	Now Examined		Tanks	Now Examined Internally	Now Tested
	YES	NO or NONE			
Shell plating, sternframe and rudder cleaned, examined and recoated in drydock			F.P. Tank	/	
Rudder lifted			A.P. "		
Weather Decks, Superstructures and Casings			D.B. Tanks (indicate Oil Fuel and Cofferdams)		
Hatchways, Covers, closing and securing appliances			Fresh Water Tanks		
Ventilator coamings, skylights, companionways and closing appliances			Deep Tanks		
Holds			Oil Fuel Bunkers and Settling Tanks		
Tween Decks			Side Tanks		
Fore Peak Spaces			Wing Tanks		
After " "			Other Tanks		
Engine Space			Cargo Tanks (Tankers)		
Boiler "			Cofferdams		
Under Engines and Boilers			Pump Rooms		
Tunnel and Well					
Coal Bunkers					
Chain Locker					
Other Spaces					

Have Tanks now Examined been Cleaned as Necessary?

Have Strums in Cargo Tanks (of Tankers) been removed?

Have Tanks been Retested as necessary after completion of any Repairs?

Have the spaces now surveyed been cleared and cleaned as necessary?

Have the close ceiling and cargo battens, linings, pipe casings, etc., been removed and replaced as required by the Rules?

Have the bilges been cleaned out and examined?

Has cement in bottom been examined?

Has steelwork had rust removed and afterwards been recoated as necessary?

Were inspection plugs or any insulation removed in insulated spaces for examination of steelwork?

Has a Load Line Survey been held? **YES** If so, state which **VERIFICATION OF SERVICE MARKINGS.**

Have the shell and deck plating been drilled as per Rule?

If so, Report 8(Dr) to be attached

Have any alterations to the approved scantlings and arrangements now been effected?

If so, report details in body of Report.

NOTE:—Indicate which compartments and/or tanks have been examined or tested by giving the identification numbers and inserting the word "Yes", e.g. Holds: Nos. 1, 2 & 3—Yes; or All—Yes.

TABLE 2

The present condition of the following parts in so far as examined is to be reported:—

Shell plating	Ceiling and Cargo Battens	Sluice Valves examined and found
" " in way of side scuttles	Cement or Asphalt	Air and Sounding Pipes
Rudder and Sternframe	Cargo and other Hatchways	Doubling Plates under Sounding Pipes
Decks	Hatches and closing appliances	Masts and Rigging examined and found
Superstructures and their closing appliances	Ventilators, their coamings and closing appliances	Condition, how ascertained (State if wedges removed)
Coamings and Casings	Companionways and Skylights	Chain Locker
Beams and Fastenings	Shell Openings	EQUIPMENT
Frames	Ash Shoots	Equipment Letter
Reverse Frames	Overboard Discharges and Scuppers	Anchors, No. of Condition
Longitudinals	Freeing ports	Cables (State if now ranged and examined)
Transverses	Steering Gear (Main and Auxiliary)	" length mean diam. (on board)
Floors	examined and found	" Rule Length Size
Keelsons	Windlass examined and found	Hawsers and Warps
Stringers	Pumps " " "	State if any Anchors or Chain Cable have
Inner Bottom Plating	W.T. Doors " " "	now been supplied or retested, if so,
Bulkheads and Tunnel		complete Report 8(Eq) and attach.

Have conditions (A) or endorsements (B) of Class (if any) been dealt with?

See Below

REMARKS, REPAIRS, Etc. (Contd.)


Survey Fee **Nil**

Second Surveyor's Fee (if any)

Special Damage or Repair Fee (if any)

Date when A/c. Rendered

Travelling Expenses (if chargeable) **Nil.**



© 2021

Lloyd's Register Foundation