

Received from Chief Ship Surveyor.....

NAME "CONCA D'ORO" REPORT PAL. No. 701

EA

Existing Conditions of Class:

SUBJECT to corroded rivets in keel and 'A' strake plating forward, also to set in shell plate No.2 in 6th strake below sheer (p.s.) being specially examined and dealt with as necessary next drydocking.

Appendix. (As before ~~or None~~)

of Present Survey: (~~Afloat and in dry dock~~)

Docking:- Examination of the above subject items.
Temporary repairs to rudder post etc.

Recommendation:

SUBMITTED record of DS 10,61 be assigned, subject as above and to permanent repairs to rudder sternpost and skeg (E.W.10,61) by 12,61.

*See Subsequent Memo
to Rpt. Palermo N° 738 of 1/62*

3.62.

DS 10,61 Subject.

IN S.R.L.APPENDIX.

Stem plating (s.s) slightly indented.
(Main structure partly of P.403 Steel).

C.S.S. Records Dept.
to note

OFFICE NOTE.

Structural arrangements in order - 25.2.55.

NOTE:-

The Surveyors report the Owners stated that a new rudder post was being ordered and arrangements for permanent repairs at Palermo would be made before the expiry of the 3 months limit.



© 2021

Hoyd's Register
Foundation

Handwritten initials/signature

17/11/61