

REPORT of SURVEY

Date of writing Report When handed in at Local Office
No. in Survey held at Date
Reg. Book.

1966 on the ~~Wood, Iron or Steel~~ "ACADIALI"
TONNAGE Built at Haverton Hill-on-Tees By
GROSS 1919 Owners Imperial Oil Ltd.
UNDER DK. 1465 Managers H.J. Rabbes
NET 1085

Surveyed Afloat or in Dry Dock? Name of Dock
WB=CellDBorDBa feet; uE&B feet; feet
total capacity tons. EPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 14028 Port Mal

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

DISCLOSED SECTION No. 728

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	E. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	State if Tanks have been examined inside	Air and Sounding Pipes	Copper, or Y.M. of Wood Vessels (state if on felt). When put on, Month Year
Decks	State if Tanks now tested	Dblng. Plates under Sounding Pipes	Boats
Caulking of Decks	Bulkheads	Engine Room Skylights	Masts, Yards, &c.
Coamings	Ceiling	Coal Bunkers, Open'gs, Lids, &c.	Condition, how ascertained (state if wedges removed)
Beams & Fastenings	Cement or Asphalt (state which.)	Oil Bunkers	Sails
Outside Plating	Rudder	Scuppers	Equipment letter
" " in way of sidelights	Steering gear and its connections	Cargo Hatchways	Anchors, No. of
Breasthooks	Windlass	Hatches	Chain Locker
Transoms	Have pumps now been examined and found efficient?	Planking of Wood Vessels	Cables (state if now ranged)
Frames	Have Sluice Valves now been examined and found efficient?	Caulking ditto	" length mean diam. (on board)
Reverse Frames	Have Watertight Doors now been examined and found efficient?	Treenails ditto	" Rule length size
Longitudinals	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson ditto	Hawser & Warps
Transverses		Transoms Pointers, & Crutches ditto	Standing and Running Riggings
Floors		Timbers of Frame at openings ditto	
Keelsons		Ditto Ditto at other places ditto	
Stringers		Stringers, Clamps & Shelves ditto	
Inner Bottom Plating		Salting (state if examined.) ditto	

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book without fresh record of Survey, "to remain as surveyed, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptnD24, &c."

FRI. 7 AUG 1966

Andrew ...
H. J. Rabbes



© 2021

Lloyd's Register Foundation

010440 - 010450 - 0210