

If the liner does not fit tightly at the part between the bearings in the stern tube, is the space charged with a plastic material insoluble in

010440-010450-0220

Acadialite

live 8557

It is concluded that the screw stays are
united on the end plates as approved, not
riveted as reported, but this should be
confirmed.

Return plans for deep.



Lloyd's Register
Foundation
15/4/30

Are all **Sea Connections** fitted direct on the skin of the ship

Are they fixed sufficiently high on the ship's side to be seen without lifting the stokehold plates

Are
yes

Are the Overboard Discharges