

If the liner does not fit tightly at the part between the bearings in the stern tube, is the space charged with a plastic material insoluble in water and

Engine No. 691190 Made by M. A. H.

For Deutsche Werft A.G. No 180

Bremen Report No. 1834

It is submitted that a copy of this Report be forwarded ~~returned~~ to the Hann Surveyors for their guidance and for completion.

Date 23.10.36



© 2024 Hann
Lloyd's Register
Foundation

To await Hann Rpt.
(copy sent by Brem.)

010440-010450-0252

Are all Sea Connections fitted direct on the skin of the ship... Are they fitted with Valves or Cocks...