

REPORT ON STEAM RECIPROCATING ENGINE MACHINERY.

Received at London Office

Date of writing Report Feb. 25th 1943 When handed in at Local Office Mch. 10th 1943 Port of MONTREAL, QUE.

No. in Survey held at MONTREAL, QUE. Date, First Survey Dec. 5th, 1942 Last Survey Jan. 27th 1943

Reg. Book. on the S. S. "FORT ENTERPRISE" (Number of Visits 30) Tons {Gross 7125.66
Net 4247.86

Built at Vancouver, B.C. By whom built West Coast Shipbuilders, Ltd. Yard No. 117. When built 1942

Engines made at LACHINE, P. Q. By whom made DOMINION ENGINEERING WORKS LTD. Engine No. 77 When made 1942

Boilers made at LACHINE, P. Q. By whom made DOMINION ENGINEERING WORKS LTD. Boiler No. 77 When made 1942

Registered Horse Power 504 Owners 505 Port belonging to 505

Nom. Horse Power as per Rule 504 Is Refrigerating Machinery fitted for cargo purposes No Is Electric Light fitted Yes

Trade for which Vessel is intended 505

ENGINES, &c.—Description of Engines Triple Expansion Revs. per minute 76

Dia of Cylinders 24½" x 37" x 70" Length of Stroke 48 No. of Cylinders 3 No. of Cranks 3

Crank shaft, dia. of journals 13.99" as per Rule 14½" as fitted 14½" Crank pin dia. 14½" Mid. length breadth — Thickness parallel to axis 9 & 9½" L.P.

Intermediate Shafts, diameter 13.33" as per Rule 13.5" as fitted 13.5" Thrust shaft, diameter at collars 13.99" as per Rule 14.25" as fitted 14.25"

Tube Shafts, diameter — as per Rule — as fitted — Screw Shaft, diameter 14.87" as per Rule 15.25" as fitted 15.25" Is the screw shaft fitted with a continuous liner Yes

Bronze Liners, thickness in way of bushes .75" as per Rule .78125" as fitted .78125" Thickness between bushes .565" as per Rule .68" as fitted .68" Is the after end of the liner made watertight in the propeller boss Yes If the liner is in more than one length are the junctions made by fusion through the whole thickness of the liner Solid

If the liner does not fit tightly at the part between the bearings in the stern tube, is the space charged with a plastic material insoluble in water and non-corrosive tight fit

If two liners are fitted, is the shaft lapped or protected between the liners — Is an approved Oil Gland or other appliance fitted at the after end of the tube —

shaft No If so, state type — Length of Bearing in Stern Bush next to and supporting propeller 61"

Propeller, dia. 18'-6" Pitch 16'-0" No. of Blades 4 Material Bronze whether Moveable Solid Total Developed Surface 117 sq. ft.

Feed Pumps worked from the Main Engines, No. None Diameter — Stroke — Can one be overhauled while the other is at work —

Bilge Pumps worked from the Main Engines, No. Two Diameter 4½" Stroke 26" Can one be overhauled while the other is at work Yes

Feed {No. and size — Pumps connected to the {No. and size —
Pumps {How driven — Main Bilge Line {How driven —

Ballast Pumps, No. and size — Lubricating Oil Pumps, including Spare Pump, No. and size —

Are two independent means arranged for circulating water through the Oil Cooler — Suctions, connected to both Main Bilge Pumps and Auxiliary Bilge Pumps:—In Engine and Boiler Room — In Holds, &c. —

Main Water Circulating Pump Direct Bilge Suctions, No. and size — Independent Power Pump Direct Suctions to the Engine Room Bilges, No. and size —

Are all the Bilge Suction Pipes in holds and tunnel well fitted with strum-boxes —

Are the Bilge Suctions in the Machinery Space led from easily accessible mud-boxes, placed above the level of the working floor, with straight tail pipes to the bilges —

Are all Sea Connections fitted direct on the skin of the ship — Are they fitted with Valves or Cocks —

Are they fixed sufficiently high on the ship's side to be seen without lifting the stokehold plates — Are the Overboard Discharges above or below the deep water line —

Are they each fitted with a Discharge Valve always accessible on the plating of the vessel — Are the Blow Off Cocks fitted with a spigot and brass covering plate —

What Pipes pass through the bunkers — How are they protected —

What pipes pass through the deep tanks — Have they been tested as per Rule —

Are all Pipes, Cocks, Valves, and Pumps in connection with the machinery and all boiler mountings accessible at all times —

Is the arrangement of Valves and their connections such as to prevent the possibility of water passing from the sea or from water tanks into the cargo or machinery spaces, or from one compartment to another — Is the Shaft Tunnel watertight — Is it fitted with a watertight door — worked from —

MAIN BOILERS, &c.—(Letter for record S) Total Heating Surface of Boilers 7140 square feet

Which Boilers are fitted with Forced Draft All three Which Boilers are fitted with Superheaters All three

No. and Description of Boilers 3 Single Ended Multitubular Working Pressure 220 lbs. per square inch

IS A REPORT ON MAIN BOILERS NOW FORWARDED? YesIS A DONKEY BOILER FITTED? NoIf so, is a report now forwarded? —Can the donkey boiler be used for domestic purposes only —PLANS. Are approved plans forwarded herewith for Shafting — Main Boilers — Auxiliary Boilers — Donkey Boilers —(If not state date of approval) Superheaters — General Pumping Arrangements — Oil fuel Burning Piping Arrangements —

SPARE GEAR.

Has the spare gear required by the Rules been supplied —State the principal additional spare gear supplied —The foregoing is a correct description
DOMINION ENGINEERING WORKS LIMITEDPer D. Van Batten

Manufacturer.

010484-010494-0238

5,7,10,11,12,14,15,16,17,18,21,22,23,28,29,30th December, 1942, 4,5,7,8,11,12,13,15,19,
During progress of work in shops - - 21,23,25,27th January, 1943
Dates of Survey while building
During erection on board vessel - - -
Total No. of visits

Dates of Examination of principal parts — Cylinders 5.1.43 23.12.42, 18.1.43 Slides 5.1.43 23.12.42, 18.1.43 Covers 5.1.43 23.12.42, 18.1.43
Pistons 5.1.43, 23.12.42, 18.1.43 Piston Rods 27.1.43 Connecting rods 27.1.43
Crank shaft 27.1.43 Thrust shaft 27.1.43 Intermediate shafts
Tube shaft Screw shaft Propeller
Stern tube Engine and boiler seatings Engines holding down bolts
Completion of fitting sea connections
Completion of pumping arrangements Boilers fixed Engines tried under steam
Main boiler safety valves adjusted Thickness of adjusting washers
Crank shaft material O H Steel Identification Mark LLOYD'S 3912 H.S.27.1.43 Thrust shaft material O H Steel Identification Mark LLOYD'S 3712 H.S.27.1.43
Intermediate shafts, material Identification Marks Tube shaft, material Identification Mark
Screw shaft, material Identification Mark Steam Pipes, material Test pressure Date of Test
Is an installation fitted for burning oil fuel No Is the flash point of the oil to be used over 150°F. - -
Have the requirements of the Rules for the use of oil as fuel been complied with - -
Is the vessel (not being an oil tanker) fitted for carrying oil as cargo If so, have the requirements of the Rules been complied with
If the notation for Ice Strengthening is desired, state whether the requirements in this respect have been complied with
Is this machinery duplicate of a previous case Yes If so, state name of vessel S/S "FORT TADOUSSAC" & S/S "FORT CHAMELY"

General Remarks (State quality of workmanship, opinions as to class, &c.) This ENGINE has been constructed under Special Survey in accordance with the Rules and Approved Plans. The materials and workmanship are good. The cylinders were tested hydrostatically to 330, 110 and 30 lbs. pressure per square inch respectively, and found tight under those pressures. This ENGINE has now been shipped to VANCOUVER, B. C., for installation and official trials. It is recommended for the favourable consideration of the Committee that the record of + L.M.C. (with date) be made in the Register Book in the case of this Vessel, subject to satisfactory installation and sea trials.

Certificate to be sent to
The Surveyors are requested not to write on or below the space for Committee's Minute.)

The amount of Entry Fee ... £/ \$30.00 : When applied for,
Special ... £/ \$267.00 : Mch. 25 1943
Donkey Boiler Fee ... £ :
Travelling Expenses (if any) £/ \$10.00 :
19

H. J. Saunders
Engineer Surveyor to Lloyd's Register of Shipping.

Committee's Minute FRI. 11 JUN 1943
Assigned See Ver. L.C. Rpt 5902.



© 2021

Lloyd's Register
Foundation