

Received from Chief Ship Surveyor

SHIP'S NAME

MIL 50

REPORT

Oslo

No. 7220

Outstanding Conditions of Class:

None

Endorsement of Class (B) (~~As before~~ or None)

Nature of Present Survey: (Afloat and in dry dock)

Docking: Permanent repairs to caused thro' encountering ice

Recommendation: Submitted the record of docking 2-53, be assigned, as recommended.

2-53 Krs.

It is further submitted the Surveyor be advised
 it is concluded that an access plate is fitted to
 the rudder side plating, for access to the coupling
 bolt nuts, but this should be confirmed.
 He should also be requested to return copy of
 rudder plan sent to him 8-4-53.

© 2021

Lloyd's Register
Foundation

010445-01050K-0147