

Reports Sep 1., Work.

"EMPIRE ALDERNEY"

F.E. Rpt.Hul.No.52469.

Before this case receives consideration the Surveyors should be informed it is concluded in the seams of the shell plating in way of the oil tanks where $\frac{3}{4}$ " rivets are required 7 pairs and where $\frac{5}{8}$ " rivets are required 8 pairs of rivets have been fitted in each frame space excluding the rivets in the frames and not 6 & 7 pairs respectively as reported, and that the rudder head is fitted with a horizontal coupling as indicated on the plan, but they should state if this is so.

They should be requested to furnish the thickness of the forecastle deck plating and the equipment number which have been omitted from their report.

X



© 2021

Handwritten signature

l.e.d
22.6.44

Lloyd's Register
Foundation

010495-010501-0231

16th June 1944