

NAME "PIENINY" REPORT H.Kg. No. 16261

GB

standing Conditions of Class: SUBJECT to forward and after bulkheads of No.3 centre cargo tank being tested on account of leakage also to forward bilge plating (s.s.) being specially examined and dealt with as found necessary, by the next drydocking and to a bower anchor and 30 fathoms of chain cable being supplied at the earliest opportunity.

Appendix. (~~As before~~ ~~or~~ None)

Condition of Present Survey: (Afloat and in dry dock)

Docking: Collision damage and equipment including part of the above subject items, also examination of cargo tanks.


Recommendation:

SUBMITTED record of 'DS 5,61' be assigned, subject to Nos. 2,3 & 4 centre tanks not being used for dissimilar cargoes until No.3 transverse bulkheads are repaired, and to port bower anchor being replaced by one in accordance with Rule requirements at the earliest opportunity, but without other conditions.

DS 5,61 Subject
Without
Amended.

ENGINEERS TO NOTE.

NOTE:- See also Ship Research Endorsement dated 18.7.61 and inform the Hong Kong Surveyors accordingly.



© 2021

Lloyd's Register
Foundation

Ag 25.7.61

24/7/61