

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

27 JUN 1950

VESSEL'S NAME EDUARD ANSEELLEN

REPORT Bhn.

No. 79

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

The BREMERHAVEN Surveyor reports (6.50) the vessel placed in dry dock, bottom coated and minor rudder repairs effected.

In consequence of damage, shell plates No. 4 in 1st and 2nd strakes below sheer (s.s.) found indented and recommended to be dealt with at Owners' convenience.

IT IS SUBMITTED the vessel be continued as classed with record of docking 6.50.

6.50 Bhn.

ENDORSEMENT OF CLASS (B)

Indents in shell plates No. 4 in 1st and 2nd below sheer (s.s.).

J.P.
27.6.50.



© 2021

Lloyd's Register
Foundation

010589 - 010604 - 0085