

5m, 7, 31.

Port

SAN FRANCISCO,

on Ship and now verified

1 *Recd*

Sent to Chief Surveyors *5. 6. 34*

Received from Chief Surveyors

VESSEL'S NAME *Sh. Le COLUMBIAN* Report *S. L.* No. *7224*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey *Completion of 2nd S.S. No 2* When due *10.33*


Noted.

S.S. No 2 34

*Yes!
13/7/34*

*W.H.B.
10.6.34*

It is concluded that the boiler space has been examined, but the Surveyor should be requested to state if this is so.



Lloyd's Register
Foundation

010605-010614-0244

Floors

Kitchens

Have Watertight Doors now been examined and found efficient?

Title Date at other places ditto

length
(on board
Rule length