

REPORT OF SURVEY FOR REPAIRS, &c.

(Received at London Office 3 5 39)

No. 107109A

Date of writing Report

When handed in at Local Office

Port of

London

No. in Reg. Book

Survey held at

Date, First Survey

Last Survey

19

86714 on the Wood, Iron or Steel

"YUKAGIR"

(No. of Visits)

TONNAGE

GROSS 1435

Built at

Yokohama

By whom Mitsubishi Yukaigyo K.K.

YEAR

MONTH

UNDER DK. 1196

Owners

U.S.S.R.

Owners' Address

(if not already recorded in Appendix to Register Book)

NET 866

Managers

Port belonging to Mummamk.

Surveyed Afloat or in Dry Dock?

Name of Dock

Destined Voyage

Disclosed Board

total capacity

feet; uE&B

feet; f

feet

tons.

Only alterations in the existing records of tanks should be inserted.

B.—All alterations in the existing records should be underlined.

Report, No. 6236

Port Yka(7E)

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER.
* for Special Survey.
Date of last Survey and of Periodical Surveys.Machinery and Boiler
Surveys
(including date of N.D., in any).

+ 100 AI

10, 37

+ Lmc 10, 37

CL

Carrying Petroleum in Bulk.
Strengthened for navigation in ice.

Oil Engine

Society's Freeboard (if assigned) as painted on Ship and now verified

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS:—

Renewed
Removed and Faired or Repaired
Faired or Repaired in place

Shell Plates.

Frames.

R. Frames.

Floors and Bracket Floors

Beams.

Inner Bottom Plates.

Dk. Plates.

Other Items:—

PRESENT CONDITION OF THE

Decks
Caulking of Decks
Coamings
Beams & Fastenings
Outside Plating
" " in way of sidelights
Frames
Reverse Frames
Longitudinals
Transverses
Floors
Keelsons
Stringers
Inner Bottom Plating
Have the Tanks been examined internally?
Have the Tanks been tested?

Bulkheads

Ceiling

Cement or Asphalt

Rudder

Steering gear and its connections

Windlass

Have pumps been examined and found efficient?

Have Sluice Valves been examined and found efficient?

Have Watertight Doors been examined and found efficient?

Have Ventilators and their Coamings been examined and found efficient?

Air and Sounding Pipes

Doubling Plates under Sounding Pipes

Engine Room Skylights

Coal Bunkers, Openings, Covers, &c.

Oil Bunkers

Scuppers

Cargo Hatchways

Hatches

Planking

Caulking

Treenails

Breasthooks & Stemson

Transoms, Pointers & Crutches

Timbers of Frame at openings

" " at other places

Stringers, Clamps & Shelves

Salting

(State if examined.)

Copper, or Y.M.
(State if on Felt.)

When fitted, Month Year

Boats

Masts, Yards, &c.

Condition, how ascertained
(State if wedges removed)

Equipment letter

Anchors, No. of

Cables (State if now ranged)

" length mean diamr.
(on board)

" Rule length size

Chain Locker

Hawsers & Warps

Standing and Running Rigging

Sails

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Survey Fee (per Section 29) £

Special Damage or Repair Fee (if any) £

Travelling Expenses (if chargeable) £

Second Surveyor's Fee (if any) £

Fees applied for,

19


Received by me,

19

Committee's Minute

Character Assigned

Surveyor to Lloyd's Register of Shipping.



Lloyd's Register Foundation

010631-010634-0209