

4E

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

S NAME

"BARBARA"

REPORT

Msl

11774

Nap

No. 5352

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.


("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey


~~REPAIRS-TO-ENGINES-AND-BOILERS-DUE-TO~~ DAMAGE THROUGH HEAVY WEATHER

Docking. Propellers and fastenings examined. The main engine circulating pump casing, which had been previously repaired, has now been renewed. Two intermediate shaft bearings have been removed, examined and refitted after repair of two fractured seatings.

IT IS SUBMITTED the vessel is eligible to remain as classed.



© 2021  
 6.4.55.



Lloyd's Register  
 Foundation

010675-010686-0084