

"L.C. 28"

F.E. Rpt. Mdb. No.17924.

It is submitted before this case receives consideration, the Surveyors be informed it is concluded the thickness of the 5" x 5" angle to the bolster plate is $5/8$ " as indicated on the plans and not $3/8$ " as reported, but they should state if this is so.

They should be requested to explain their recommendation for assignment of the figure '1' in view of the total length of chain cables reported on board being considerably below that specified by the Admiralty for and supplied to the previous sister vessels.

J.C.D.
2.11.45.

B.H.H.



© 2021

Lloyd's Register
Foundation

010705- 010711- 0029