

EA

COPY

Ship's name "HENRIETTA"

Port

MSL.

No. 13579

Last survey date 15.2.63.

Class is subject to

indented shell plate between frs. 21-25 in way of main deck (p.s) being specially examined and dealt with as necessary next drydocking, and to indented bottom shell plating in 'C' & 'D' strakes abreast No. 1 wing tank (p.s) being specially examined and dealt with as necessary by the Special Survey.  
ACTION is DEFERRED for Special Survey.

S.R.L. Appendix (as before ~~or none~~)

Surveys due

SPECIAL SURVEY (C) due 8.62. Postponement until 8.63 approved 16.1.63 following a satisfactory G.E.

Nature of present survey (afloat and ~~in~~ drydock)

Deferred repairs to collision damage.

Is interim certificate in order

Yes/No/None

Items outstanding if any for SS

ALL ITEMS.

SS proposed to be completed by 8.63.

Recommendation

SUBJECT as above and to indented shell plate G.19 (s.s) and structure in way being specially examined and dealt with as necessary by the next drydocking, but ACTION continue to be DEFERRED for Special Survey by 8.63.

SUBJECT.

~~IN S.R.L. APPENDIX~~

Indents in a few side shell plates (p.s).



© 2021

Lloyd's Register  
Foundation