

COPY

Ship's name

CHOPIN

Port

Gdk

No. M. 1143


Last survey date 28.12.62

Class is subject to

nil

Small crack in the welding of distance
piece of auxiliary boiler blowdown
seawave to the ship's side. Surveyor
recommends distance piece for aux.
boiler blowdown seawave repaired by
a cement box be examined and
deck with as necessary at next dry-
docking

*It is submitted that this
vessel is eligible to remain
as CLASSED: subject as above*



© 2021

Lloyd's Register
Foundation