

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 8695 Port *Dun*

CHARACTER.  
\* for Special Survey.  
Date of last Survey and of  
Periodical Surveys.

\* A -

For service on the *Ta*

2m, 11.32.

## POSTPONED SURVEYS.

Case of the

*Rad*  
Steel ~~S.S.~~ "B.L. NAIRN"

No. *06824* in Reg. Bk. *3957171* tons, Built *1929 - 6 mo*

Classed *+A-*  
*In service*  
*the day*  
*6.12.29* + LMC 6.29 Owners *Trustees of the Harbour of Dundee*  
Port of Registry *Dundee*

Survey Due

Special Survey No.1 due June, 1933

Proposed to be held within the year of grace

*Submitted for approval.*  
*GRD.* *AL*  
*17.7.33*

Committee's Minute *TUE 18 JUL 1933*

Decision

*Approved*

*WJ*

Copper, or Y.M. of  
(State if on Fe  
When put on, M

Boats

Masts, Yards, &c.

Condition, how ascer

(State if wedg

Sails

Equipment letter

Anchors, No. of

Cables (State if nou

length

(on board

Rule length

Hawser & Warps

Standing and Runnin

in the Register  
main as classed a



© 2021

Lloyd's Register  
Foundation

010874-010881-0023  
010874-010881-0024

Survey Fee (per section 20) £

Fees applied for,

19

Special Damage or Repair Fee (if any) £