

Ship's name

"MOBIL RADIANT"

Port

19-SEP 1963

MEL

No. 20783

Last survey date 6.8.63

Class is subject to

The Outboard turbo generator turbine being specially examined at next dry docking and by 6.64.

---

Starboard main boiler examined for damage stated caused by side wall tube bursting. 38 side wall tubes found sagged and one tube split for about 18". All these tubes now renewed. The first 8 rear wall tubes from the inboard side bowed about 2" and some other tubes slightly bowed. Surveyor recommends they be examined at the next MBS.

IT IS SUBMITTED that this vessel is eligible to remain as classed subject to the rear wall tubes in the Starboard boiler being specially examined at the next Boiler Survey, also subject as above.



© 2021

*Handwritten signature*

3.9.63

Lloyd's Register  
Foundation